

Division of Health Service Regulation

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION	(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER: MHL082-056	(X2) MULTIPLE CONSTRUCTION A. BUILDING: _____ B. WING _____	(X3) DATE SURVEY COMPLETED R 09/11/2018
--	---	---	---

NAME OF PROVIDER OR SUPPLIER CANDII HOMES	STREET ADDRESS, CITY, STATE, ZIP CODE 404 EAST POWELL STREET CLINTON, NC 28328
---	--

(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)	(X5) COMPLETE DATE
V 000	INITIAL COMMENTS An annual and follow up survey was completed on September 11, 2018. A deficiency was cited. This facility is licensed for the following service category: 10A NCAC 27G .5600C Supervised Living for Adults with Developmental Disabilities.	V 000		
V 752	27G .0304(b)(4) Hot Water Temperatures 10A NCAC 27G .0304 FACILITY DESIGN AND EQUIPMENT (b) Safety: Each facility shall be designed, constructed and equipped in a manner that ensures the physical safety of clients, staff and visitors. (4) In areas of the facility where clients are exposed to hot water, the temperature of the water shall be maintained between 100-116 degrees Fahrenheit. This Rule is not met as evidenced by: Based on observation and interview, the facility failed to maintain the water temperature between 100-116 degrees Fahrenheit. The findings are: Observation on 09/11/18 at approximately 11:45am of the facility revealed the hot water temperature in the kitchen sink and clients bathroom was 124 degrees Fahrenheit. Interview on 09/11/18 the Qualified Professional stated: - She had contacted someone to turn the temperature of the hot water heater down and would make the necessary temperature adjustment.	V 752		

LABORATORY DIRECTOR'S OR PROVIDER/SUPPLIER REPRESENTATIVE'S SIGNATURE	TITLE	(X6) DATE
---	-------	-----------