

Division of Health Service Regulation

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION	(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER: MHL076-068	(X2) MULTIPLE CONSTRUCTION A. BUILDING: _____ B. WING _____	(X3) DATE SURVEY COMPLETED 03/14/2019
--	---	---	---

NAME OF PROVIDER OR SUPPLIER YOUTH UNLIMITED HAYWORTH HOME	STREET ADDRESS, CITY, STATE, ZIP CODE 2748 YOUTH UNLIMITED DRIVE SOPHIA, NC 27350
--	---

(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)	(X5) COMPLETE DATE
V 000	<p>INITIAL COMMENTS</p> <p>An annual survey was completed on 3/14/19. Deficiencies were cited.</p> <p>This facility is licensed for the following service category: 10A NCAC 27G .1700 Residential Treatment Staff Secure for Children or Adolescents.</p>	V 000		
V 752	<p>27G .0304(b)(4) Hot Water Temperatures</p> <p>10A NCAC 27G .0304 FACILITY DESIGN AND EQUIPMENT (b) Safety: Each facility shall be designed, constructed and equipped in a manner that ensures the physical safety of clients, staff and visitors. (4) In areas of the facility where clients are exposed to hot water, the temperature of the water shall be maintained between 100-116 degrees Fahrenheit.</p> <p>This Rule is not met as evidenced by: Based on observation and interviews the facility failed to maintain the facility water temperature between 100-116 degrees Fahrenheit. The findings are:</p> <p>Observation of the facility on 3/13/19 at approximately 9:13 AM revealed : -The kitchen sink water temperature was 130 degrees Fahrenheit. -Bathroom #1 water temperature was 130 degrees Fahrenheit.</p> <p>Interview with clients' #1, #2 and #3 on 3/13/19 revealed: -They were all capable of adjusting their own water temperature during bathing.</p>	V 752		

Division of Health Service Regulation
LABORATORY DIRECTOR'S OR PROVIDER/SUPPLIER REPRESENTATIVE'S SIGNATURE _____ TITLE _____ (X6) DATE _____

Division of Health Service Regulation

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION	(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER: MHL076-068	(X2) MULTIPLE CONSTRUCTION A. BUILDING: _____ B. WING _____	(X3) DATE SURVEY COMPLETED 03/14/2019
--	---	---	---

NAME OF PROVIDER OR SUPPLIER YOUTH UNLIMITED HAYWORTH HOME	STREET ADDRESS, CITY, STATE, ZIP CODE 2748 YOUTH UNLIMITED DRIVE SOPHIA, NC 27350
--	---

(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)	(X5) COMPLETE DATE
V 752	<p>Continued From page 1</p> <p>-They did not require any assistance from staff.</p> <p>Interview with staff #1 on 3/13/19 revealed: -All four clients were capable of adjusting their own water temperatures during bathing.</p> <p>Interview with the Facility Director on 3/14/19 confirmed: -The facility failed to maintain the facility water temperature between 100-116 degrees Fahrenheit.</p> <p>Interview with the Clinical Director on 3/13/19 revealed: -The group home had two separate hot water heaters -They just recently installed a new hot water heater. -The newer hot water heater was near the kitchen and bathroom #1. -All four clients were capable of adjusting their own water temperature during bathing. -He confirmed the facility failed to maintain the facility water temperature between 100-116 degrees Fahrenheit.</p>	V 752		