

Division of Health Service Regulation

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION	(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER: mh1060-907	(X2) MULTIPLE CONSTRUCTION A. BUILDING: _____ B. WING _____	(X3) DATE SURVEY COMPLETED R 01/09/2020
--	---	---	---

NAME OF PROVIDER OR SUPPLIER JIREH'S PLACE, INC	STREET ADDRESS, CITY, STATE, ZIP CODE 5128 ROSEMEDE DRIVE CHARLOTTE, NC 28227
---	---

(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)	(X5) COMPLETE DATE
V 000	<p>INITIAL COMMENTS</p> <p>An annual and follow up survey was completed on 1/9/20. A deficiency was cited.</p> <p>This facility is licensed for the following service category: 10A NCAC 27G .5600F Supervised Living/ Alternative Family Living</p>	V 000		
V 752	<p>27G .0304(b)(4) Hot Water Temperatures</p> <p>10A NCAC 27G .0304 FACILITY DESIGN AND EQUIPMENT</p> <p>(b) Safety: Each facility shall be designed, constructed and equipped in a manner that ensures the physical safety of clients, staff and visitors.</p> <p>(4) In areas of the facility where clients are exposed to hot water, the temperature of the water shall be maintained between 100-116 degrees Fahrenheit.</p> <p>This Rule is not met as evidenced by: Based on observation and interview the facility failed to maintain hot water between 100 and 116 degrees in areas where clients had access to water. The findings are:</p> <p>Observation on 1/9/20 at approximately 2:15pm revealed: - hot water temperature in the bathroom sink and shower read 120 degrees Fahrenheit (F) - hot water temperature in the kitchen sink read 120 degrees F</p> <p>Interview on 1/9/20 with The licensee/ AFL Provider revealed: - They just had a new water heater put in October 2019. One time, the water was not hot enough and now its too hot. They were trying to find the</p>	V 752		

Division of Health Service Regulation LABORATORY DIRECTOR'S OR PROVIDER/SUPPLIER REPRESENTATIVE'S SIGNATURE	TITLE	(X6) DATE
--	-------	-----------

Division of Health Service Regulation

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION	(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER: mh1060-907	(X2) MULTIPLE CONSTRUCTION A. BUILDING: _____ B. WING _____	(X3) DATE SURVEY COMPLETED R 01/09/2020
--	---	---	---

NAME OF PROVIDER OR SUPPLIER JIREH'S PLACE, INC	STREET ADDRESS, CITY, STATE, ZIP CODE 5128 ROSEMEDE DRIVE CHARLOTTE, NC 28227
---	---

(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)	(X5) COMPLETE DATE
V 752	<p>Continued From page 1</p> <p>correct balance.</p> <p>- Client #1 requires assistance with setting water temperature and daily hygiene</p> <p>This deficiency is a re-cited deficiency and must be corrected within 30 days.</p>	V 752		