

Division of Health Service Regulation

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION	(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER: MHL092-866	(X2) MULTIPLE CONSTRUCTION A. BUILDING: _____ B. WING _____	(X3) DATE SURVEY COMPLETED R 02/12/2020
--	---	---	---

NAME OF PROVIDER OR SUPPLIER HEAVENLY PLACE, LLC	STREET ADDRESS, CITY, STATE, ZIP CODE 8600 NEUSE HUNTER DRIVE RALEIGH, NC 27616
--	---

(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)	(X5) COMPLETE DATE
V 000	<p>INITIAL COMMENTS</p> <p>An Annual and Follow Up Survey was completed 02/12/20. A deficiency was cited.</p> <p>This facility is licensed for the following service category: 10A NCAC 27G .5600C Supervised Living for Adults with Developmental Disabilities.</p>	V 000		
V 736	<p>27G .0303(c) Facility and Grounds Maintenance</p> <p>10A NCAC 27G .0303 LOCATION AND EXTERIOR REQUIREMENTS (c) Each facility and its grounds shall be maintained in a safe, clean, attractive and orderly manner and shall be kept free from offensive odor.</p> <p>This Rule is not met as evidenced by: Based on observation and interview, the governing body failed to assure the facility and grounds were maintained in a safe and attractive manner. The findings are:</p> <p>Observation on 02/10/20 12:45 PM - 1:00 PM revealed:</p> <ul style="list-style-type: none"> - First room: cluttered, sheetrock not flush connecting walls - Hallways: thick dust noted near air vent, ceiling peeling - Master bathroom: ceiling peeling near the vent, water stain noted - Third Bedroom: door damaged, light switch broken -Fourth Bedroom: hole in the door -Hallway bathroom: ceiling peeling 	V 736		

Division of Health Service Regulation
LABORATORY DIRECTOR'S OR PROVIDER/SUPPLIER REPRESENTATIVE'S SIGNATURE _____ TITLE _____ (X6) DATE _____

Division of Health Service Regulation

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION	(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER: MHL092-866	(X2) MULTIPLE CONSTRUCTION A. BUILDING: _____ B. WING _____	(X3) DATE SURVEY COMPLETED R 02/12/2020
--	---	---	---

NAME OF PROVIDER OR SUPPLIER HEAVENLY PLACE, LLC	STREET ADDRESS, CITY, STATE, ZIP CODE 8600 NEUSE HUNTER DRIVE RALEIGH, NC 27616
--	---

(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)	(X5) COMPLETE DATE
V 736	<p>Continued From page 1</p> <p>During interview on 02/10/20, staff #1 reported: -She would report the concerns to Maintenance -Prior to interview, had not noticed the identified violations</p> <p>During interview on 02/11/20, the Qualified Professional reported: -She had contacted the facility's maintenance department to resolve the violations identified.</p>	V 736		