

Division of Health Service Regulation

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION	(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER: MHL060-616	(X2) MULTIPLE CONSTRUCTION A. BUILDING: _____ B. WING _____	(X3) DATE SURVEY COMPLETED 07/20/2021
--	---	---	---

NAME OF PROVIDER OR SUPPLIER THE KID'S WORKSHOP	STREET ADDRESS, CITY, STATE, ZIP CODE 5901 BEATTIES FORD ROAD CHARLOTTE, NC 28216
---	---

(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)	(X5) COMPLETE DATE
V 000	<p>INITIAL COMMENTS</p> <p>An annual and complaint survey was completed on 7-20-21. The complaint was unsubstantiated (#NC00178557). A deficiency was cited.</p> <p>This facility is licensed for the following service category: 10A NCAC 27G 2200 Before/After School and Summer Developmental Day Services for Children With or At Risk for Developmental Delays, Developmental Disabilities, or Atypical Development.</p>	V 000		
V 752	<p>27G .0304(b)(4) Hot Water Temperatures</p> <p>10A NCAC 27G .0304 FACILITY DESIGN AND EQUIPMENT</p> <p>(b) Safety: Each facility shall be designed, constructed and equipped in a manner that ensures the physical safety of clients, staff and visitors.</p> <p>(4) In areas of the facility where clients are exposed to hot water, the temperature of the water shall be maintained between 100-116 degrees Fahrenheit.</p> <p>This Rule is not met as evidenced by: Based on observation and interview the facility failed to maintain hot water between 100 degrees and 116 degrees in areas where client have access to hot water.</p> <p>Observation on 6-29-21 at approximately 3:00 pm revealed: -Hall bathroom sink was 90 degrees. -Classroom sink was 60 degrees. -Back hall bathroom sink was 90 degrees. -Double sink bathroom, sink #1 was 92 degrees, sink #2 was 92 degrees.</p>	V 752		

Division of Health Service Regulation LABORATORY DIRECTOR'S OR PROVIDER/SUPPLIER REPRESENTATIVE'S SIGNATURE	TITLE	(X6) DATE
--	-------	-----------

Division of Health Service Regulation

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION	(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER: MHL060-616	(X2) MULTIPLE CONSTRUCTION A. BUILDING: _____ B. WING _____	(X3) DATE SURVEY COMPLETED 07/20/2021
--	---	---	---

NAME OF PROVIDER OR SUPPLIER THE KID'S WORKSHOP	STREET ADDRESS, CITY, STATE, ZIP CODE 5901 BEATTIES FORD ROAD CHARLOTTE, NC 28216
---	---

(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)	(X5) COMPLETE DATE
V 752	Continued From page 1 Interview on 6-29-21 with the Director revealed: -She didn't know why the water temperature was so different at the different sinks. -They would have someone fix the temperature as soon as possible.	V 752		