

Division of Health Service Regulation

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION	(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER: mhl064-074	(X2) MULTIPLE CONSTRUCTION A. BUILDING: _____ B. WING _____	(X3) DATE SURVEY COMPLETED R 01/27/2022
--	---	---	---

NAME OF PROVIDER OR SUPPLIER CAROLINA BLUE WATERS	STREET ADDRESS, CITY, STATE, ZIP CODE 130 JONES ROAD ROCKY MOUNT, NC 27804
---	--

(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)	(X5) COMPLETE DATE
V 000	<p>INITIAL COMMENTS</p> <p>An annual, complaint and follow up survey was completed on 1/27/22. The complaints were unsubstantiated (Intake #NC00182910 & NC00182763). Deficiencies were cited.</p> <p>This facility is licensed for the following service category: 10A NCAC 27G .1200 Psychosocial Rehabilitation Facilities for Individuals with Severe and Persistent Mental Illness.</p> <p>The survey sample consisted of audits of 3 current clients and 3 former clients.</p>	V 000		
V 752	<p>27G .0304(b)(4) Hot Water Temperatures</p> <p>10A NCAC 27G .0304 FACILITY DESIGN AND EQUIPMENT (b) Safety: Each facility shall be designed, constructed and equipped in a manner that ensures the physical safety of clients, staff and visitors. (4) In areas of the facility where clients are exposed to hot water, the temperature of the water shall be maintained between 100-116 degrees Fahrenheit.</p> <p>This Rule is not met as evidenced by: Based on interview and observation, the facility did not ensure where clients were exposed to hot water that the hot water temperature was between 100 - 116 degrees Fahrenheit. The findings are:</p> <p>Observation on 1/25/22 at 10:20am revealed: -Male bathroom sink water temperature was 122 degrees Fahrenheit. -Female bathroom sink water temperature was 122 degrees Fahrenheit.</p>	V 752		

Division of Health Service Regulation
LABORATORY DIRECTOR'S OR PROVIDER/SUPPLIER REPRESENTATIVE'S SIGNATURE _____ TITLE _____ (X6) DATE _____

Division of Health Service Regulation

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION	(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER: mhl064-074	(X2) MULTIPLE CONSTRUCTION A. BUILDING: _____ B. WING _____	(X3) DATE SURVEY COMPLETED R 01/27/2022
--	---	---	---

NAME OF PROVIDER OR SUPPLIER CAROLINA BLUE WATERS	STREET ADDRESS, CITY, STATE, ZIP CODE 130 JONES ROAD ROCKY MOUNT, NC 27804
---	--

(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)	(X5) COMPLETE DATE
V 752	Continued From page 1 Interview on 1/25/22 the Qualified Professional reported: -She didn't know the water temperature was that high. -These were the only sinks that the clients used. -She would make sure the water temperature was adjusted within the range that the state allowed.	V 752		