

Division of Health Service Regulation

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION	(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER: MHL032-586	(X2) MULTIPLE CONSTRUCTION A. BUILDING: _____ B. WING _____	(X3) DATE SURVEY COMPLETED R 09/09/2022
--	---	---	---

NAME OF PROVIDER OR SUPPLIER RECOVERY CONNECTIONS I	STREET ADDRESS, CITY, STATE, ZIP CODE 2203 ELMWOOD AVENUE DURHAM, NC 27707
---	--

(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)	(X5) COMPLETE DATE
V 000	<p>INITIAL COMMENTS</p> <p>An annual and follow-up survey was completed on September 9, 2022. A deficiency was cited.</p> <p>This facility is licensed for the following service category: 10A NCAC 27G .5600E Supervised Living for Adults with Substance Dependency.</p> <p>This facility is licensed for 6 and currently has a census of 5. The survey sample consisted of audits of 3 current clients.</p>	V 000		
V 752	<p>27G .0304(b)(4) Hot Water Temperatures</p> <p>10A NCAC 27G .0304 FACILITY DESIGN AND EQUIPMENT</p> <p>(b) Safety: Each facility shall be designed, constructed and equipped in a manner that ensures the physical safety of clients, staff and visitors.</p> <p>(4) In areas of the facility where clients are exposed to hot water, the temperature of the water shall be maintained between 100-116 degrees Fahrenheit.</p> <p>This Rule is not met as evidenced by: Based on observation and interview the facility failed to maintain the facility water temperature between 100-116 degrees Fahrenheit. The findings are:</p> <p>Observation of the facility on 9/9/22 at approximately 11:50 am revealed : -The kitchen sink water temperature was 129 degrees Fahrenheit.</p> <p>Interview on 9/9/22 with the Facility Manager on revealed: -She did not realize the water temperature was</p>	V 752		

Division of Health Service Regulation
LABORATORY DIRECTOR'S OR PROVIDER/SUPPLIER REPRESENTATIVE'S SIGNATURE _____ TITLE _____ (X6) DATE _____

Division of Health Service Regulation

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION	(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER: MHL032-586	(X2) MULTIPLE CONSTRUCTION A. BUILDING: _____ B. WING _____	(X3) DATE SURVEY COMPLETED R 09/09/2022
--	---	---	---

NAME OF PROVIDER OR SUPPLIER RECOVERY CONNECTIONS I	STREET ADDRESS, CITY, STATE, ZIP CODE 2203 ELMWOOD AVENUE DURHAM, NC 27707
---	--

(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)	(X5) COMPLETE DATE
V 752	Continued From page 1 129 degrees. -Clients were capable of adjusting the hot water temperature in the kitchen or bathroom area. -Maintenance person was supposed to visit the house to check on the water temperature since it had been cited at sister facilities, but never got to do it before the survey. -She confirmed the facility failed to maintain the water temperature between 100-116 degrees Fahrenheit.	V 752		