

Division of Health Service Regulation

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION		(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER: MHL024-121	(X2) MULTIPLE CONSTRUCTION A. BUILDING: _____ B. WING: _____	(X3) DATE SURVEY COMPLETED 06/27/2025
NAME OF PROVIDER OR SUPPLIER LCBHS-44 MAPLE LANE		STREET ADDRESS, CITY, STATE, ZIP CODE 44 MAPLE LANE CHADBOURN, NC 28431		
(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)	(X5) COMPLETE DATE
V 000	<p>INITIAL COMMENTS</p> <p>An annual survey was completed on June 27, 2025. A deficiency was cited.</p> <p>This facility is licensed for the following service category: 10A NCAC 27G .5100 Community Respite Services for Individuals of all Disability Groups.</p> <p>This facility is licensed for 2 and currently has a census of 1. The survey sample consisted of an audit of 1 current client.</p>	V 000		
V 752	<p>27G .0304(b)(4) Hot Water Temperatures</p> <p>10A NCAC 27G .0304 FACILITY DESIGN AND EQUIPMENT (b) Safety: Each facility shall be designed, constructed and equipped in a manner that ensures the physical safety of clients, staff and visitors. (4) In areas of the facility where clients are exposed to hot water, the temperature of the water shall be maintained between 100-116 degrees Fahrenheit.</p> <p>This Rule is not met as evidenced by: Based on observation and interview, the facility water temperatures were not maintained between 100-116 degrees Fahrenheit in areas where clients were exposed to hot water. The findings are:</p> <p>Observation on 6/27/25 at approximately 10:15am revealed: -The hot water temperature in bathroom #1 was 120 degrees Fahrenheit at the sink. -The hot water temperature at the kitchen sink was 122 degrees Fahrenheit.</p>	V 752		

Division of Health Service Regulation

LABORATORY DIRECTOR'S OR PROVIDER/SUPPLIER REPRESENTATIVE'S SIGNATURE

TITLE

(X6) DATE

Division of Health Service Regulation

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION		(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER: MHL024-121	(X2) MULTIPLE CONSTRUCTION A. BUILDING: _____ B. WING: _____	(X3) DATE SURVEY COMPLETED 06/27/2025
NAME OF PROVIDER OR SUPPLIER LCBHS-44 MAPLE LANE		STREET ADDRESS, CITY, STATE, ZIP CODE 44 MAPLE LANE CHADBOURN, NC 28431		
(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)	(X5) COMPLETE DATE
V 752	Continued From page 1 Interview on 6/27/25 client #1 stated he had no issues with water temperature. Interview on 6/27/25 supervisor stated she would follow up to ensure the proper range of water temperature was maintained.	V 752		