

Division of Health Service Regulation

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION		(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER: MHL0601067	(X2) MULTIPLE CONSTRUCTION A. BUILDING: _____ B. WING: _____	(X3) DATE SURVEY COMPLETED R 07/28/2025
NAME OF PROVIDER OR SUPPLIER ECHELON 5		STREET ADDRESS, CITY, STATE, ZIP CODE 1535 PEACHTREE ROAD CHARLOTTE, NC 28216		
(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)	(X5) COMPLETE DATE
V 000	<p>INITIAL COMMENTS</p> <p>A complaint and follow up survey was completed on 7-28-25. The complaint was unsubstantiated (#NC00231249). A deficiency was cited.</p> <p>This facility is licensed for the following service category: 10A NCAC 27G .1700 Residential Treatment Staff Secure for Children or Adolescents.</p> <p>This facility is licensed for 4 and currently has a census of 3. The survey sample consisted of audits of 1 current client.</p>	V 000		
V 736	<p>27G .0303(c) Facility and Grounds Maintenance</p> <p>10A NCAC 27G .0303 LOCATION AND EXTERIOR REQUIREMENTS</p> <p>(c) Each facility and its grounds shall be maintained in a safe, clean, attractive and orderly manner and shall be kept free from offensive odor.</p> <p>This Rule is not met as evidenced by: Based on observation and interviews the facility failed to be maintained in a safe, clean, and attractive manner. The findings are:</p> <p>Observation on July 23, 2025 at approximately 3:00pm revealed:</p> <ul style="list-style-type: none"> -Kitchen: section of floor has 6 squares of linoleum that do not match the others, and are broken on the sides, 1/2 of the curtain paneling on the deck door was closed in the door to keep it from falling. -Back bathroom in Client #1's room: linoleum dirty and broken, floor is soggy around the shower, one wall has the paint and sheet rock chipped and broken. -Hallway and den: Carpet stained, torn, and 	V 736		

Division of Health Service Regulation

LABORATORY DIRECTOR'S OR PROVIDER/SUPPLIER REPRESENTATIVE'S SIGNATURE

TITLE

(X6) DATE

Division of Health Service Regulation

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION		(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER: MHL0601067	(X2) MULTIPLE CONSTRUCTION A. BUILDING: _____ B. WING: _____	(X3) DATE SURVEY COMPLETED R 07/28/2025
NAME OF PROVIDER OR SUPPLIER ECHELON 5		STREET ADDRESS, CITY, STATE, ZIP CODE 1535 PEACHTREE ROAD CHARLOTTE, NC 28216		
(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)	(X5) COMPLETE DATE
V 736	<p>Continued From page 1</p> <p>worn through out the area, vent in the hallway is covered with dark crime.</p> <p>Interview on 7-28-25 with the Qualified Professional revealed:</p> <ul style="list-style-type: none"> -They had been trying to make improvements, but the landlord has not approved some of the changes. -The curtain being held up by the closed door was "ridiculous". <p>This deficiency constitutes a recited deficiency and must be corrected within 30 days.</p>	V 736		